12 DEC 68 00 007

	·	•	
S E C R E T 112347Z DEC 68 CITE 5234			25 X 1
PRIORITY 7234			25X1
SUBJECT: EVALUATION OF GLASS LAMP MISSION G-056	مرا المام الما المام المام ال		
1. IMAGE QUALITY: THE OVERALL IMAGE QUALITY OF THIS MIS			
IS FAIR. THE IMAGERY IN THE VERTICAL POSITION PHOTOGRAPHS I			0 E V 4
THAN THE IMAGERY IN THE 1L AND OUT OF FOCUS. THERE ARE INST			25 X 1
GOOD IMAGERY INTERMITTENTLY IN THE MISSION. THE INTERPRETAT			
BILITY OF THIS MISSION IS FAIR. CLOUD COVER AND HAZE OBSCUR			
MATELY 25 PERCENT OF THE MISSION.			
2. MISSION DATA:			
A. GLASS LAMP MISSION G-056 WAS FLOWN ON 6 DECEMBER 19		HE	
STANDARD "B" CONFIGURATION CAMERA, UNIT NUMBER 26, WAS USED. B. FILM TYPE 3401 WAS USED THROUGHOUT. PROCESSING WAS			,
PLISHED BY NAV RECON TECH SUPPCEN.	ACCOM.	•	
3. ORIGINAL NEGATIVE:	**		
A. EXPOSURE: THE EXPOSURE THROUGHOUT MOST OF THE MISS			
ADEQUATE; HOWEVER, THE END OF THE MISSION APPEARS TO BE SLIG			
OVER-EXPOSED.			
B. DENSITY AND CONTRAST: THE DENSITY AND CONTRAST ARE			
	DIS	TRIBUTION	
	CX	OFFICE	Pl
		ABLE SEC.	
PAGE 2 5234 S.E.C.R.E.T.			25X1
GENERALLY MEDIUM; HOWEVER, THE END OF THE MISSION IS MORE DEA WITH LOWER CONTRAST.		ECUR.	V
C. IMAGE DEGRADATIONS:	34	ss/APSD	
(1) SR SIDE: ROLLER CHATTER IS PRESENT ALONG THE INE	OARD P	SG/00	-
EDGE. NUMEROUS MINUS DENSITY SPOTS. GRANDULAR-LIKE IN APPEAR	ANCE,	RED	
ARE PRESENT IN A Ø.25 INCH WIDE BAND ALONG THE INBOARD EDGE O		REPRO	
THE FIRST 150 FRAMES. THE SPOTS APPEAR TO BE PROCESSING INDU IN THAT THEY APPEAR IN THE CLOCK IMAGE AS WELL AS THE TERRAIN	.; • 1	AID	
IMAGERY. A PLUS DENSITY LINE IS PRESENT THROUGHOUT THE MISSI		EG ,	<u> </u>
PARALLEL TO THE MAJOR AXIS OF THE FILM. 4.0 INCHES FROM THE O		PROD	-
BOARD EDGE. FRAME 6 CONTAINS LIGHT LEAK INDUCED FOG.	1	WEST	-
(2) 9L SIDE: SEE BOTH SIDES.		EAST	de a cerei
(3) BOTH SIDES: FRAME ØØ1 CONTAINS FOG ASSOCIATED WI	5	M&S	1
LIGHT LEAK AND IS DOUBLE EXPOSED. EDGE FOG IS PRESENT ALONG INBOARD AND BOTH OUTBOARD EDGES.	1 1	PGM	
D. PHSICAL DEGRADATIONS:		AS	-
(1) SR SIDE: FRAME 2 CONTAINS SEVERAL EMULSION		DIA-XX4	Jan-
SCRATCHES. TWO EMULSION DEFECTS ARE PRESENT IN FRAME 764.		SPAD DIA-AP	-
IWO HEAT SPLICES AND A MANUFACTURING SPLICE ARE PRESENT IN TH	E -	With the But Start State State	25X1
MISSION MATERIAL.		CMX	1
			1,,
randra eta erregio de la companya d La companya de la co		and the second second	
	61	OVARCE OF	
	/9	・ シェナマモルを持ち込む	
Profig 3 5234 S E C R E T	ÜV	ITH TEXE	∠5 X 1
(2) SL SIDE: TWO MANUFACTURING SPLICES ARE PRESENT I	NTHE	· 3.	
E. AUXILIARY DATA: THE EVENTS COUNTER SKIPPED NUMBER 2	934 -		

Approved For Release 2008/01/22 : CIA-RDP78B04549A001100030145-3

OTHER DATA RECORDING EQUIPMENT FUNCTIONED PROPERLY.

END OF MSG

F. OTHER: THE LAST TITLED FRAME IS 2937.

4. POSITIVES:
A. THE PRINTING AND PROCESSING ARE GOOD.
SECRET